

ICC-ES Evaluation Report

ESR-3074 FBC Supplement

Reissued July 2023 This report is subject to renewal July 2025.

www.icc-es.org | (800) 423-6587 | (562) 699-0543

A Subsidiary of the International Code Council®

DIVISION: 31 00 00—EARTHWORK Section: 31 63 00—Bored Piles

REPORT HOLDER:

SUPPORTWORKS, INC.

EVALUATION SUBJECT:

SUPPORTWORKS HELICAL FOUNDATION SYSTEMS

1.0 REPORT PURPOSE AND SCOPE

Purpose:

The purpose of this evaluation report supplement is to indicate that the Supportworks, Inc. (Supportworks) Models HP288 and HP350 Helical Foundation Systems, described in ICC-ES evaluation report ESR-3074, have also been evaluated for compliance with the codes noted below.

Applicable code editions:

- 2020 Florida Building Code—Building
- 2020 Florida Building Code—Residential

2.0 CONCLUSIONS

The Supportworks Models HP288 and HP350 Helical Foundation Systems, described in Sections 2.0 through 7.0 of the evaluation report ESR-3074, comply with the *Florida Building Code—Building* and the *Florida Building Code—Residential*, provided the design requirements are determined in accordance with the in accordance with the *Florida Building Code—Building Code—Building Code—Residential*, as applicable. The installation requirements noted in ICC-ES evaluation report ESR-3074 for the 2018 *International Building Code*® meet the requirements of the *Florida Building Code—Building Code—Building Code—Residential*.

Use of the Supportworks Models HP288 and HP350 Helical Foundation Systems for compliance with the High-Velocity Hurricane Zone provisions of the *Florida Building Code—Building* and the *Florida Building Code—Residential* has not been evaluated, and is outside the scope of this evaluation report.

For products falling under Florida Rule 61G20-3, verification that the report holder's quality-assurance program is audited by a quality-assurance entity approved by the Florida Building Commission for the type of inspections being conducted is the responsibility of an approved validation entity (or the code official, when the report holder does not possess an approval by the Commission).

This supplement expires concurrently with the evaluation report ESR-3074, reissued July 2023.

